

SECRET

OUT52480

1

S E C R E T 170115Z

1963 DEC 17 01 25Z

25X1

1. CAMERA B 7 WAS USED IN MISSION 3794 FLOWN ON 14 DECEMBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: PLUS DENSITY STREAKS PARALLEL TO THE MAJOR AXIS OF THE FILM ARE INTERMITTENT THROUGHOUT THE MISSION ABOUT 1.0", 3.0", AND 8.0" FROM THE NONTITLED EDGE. AN EMULSION LIFT APPROXIMATELY 0.5" LONG WITH ASSOCIATED KINKS EXISTS IN FRAME 2598. FOREIGN MATTER IS PRESENT ON FRAMES 2435 AND 2511. PARTS 5, 6 AND 14 WERE MISLABLED. MANUFACTURING SPLICES WITH ASSOCIATED WRINKLING ARE PRESENT IN FRAMES 010 AND 1330.

C. 9L SIDE: INBOARD ROLLER CHATTER IS CONTINUOUS ON THE FIRST 25 PER CENT OF THE MISSION. EDGE STATIC IS INTERMITTENT ON BOTH EDGES THROUGHOUT THE MISSION. THE POSITION INDICATOR LAMPS FAILED ON ALL POSITIONS EXCEPT THE "V" AND "1R". HEAVY DEPOSITS OF FOREIGN MATTER APPEAR ON THE BASE SIDE OF FRAMES 360-370. INTERMITTENT, WAVERING PLUS DENSITY STREAKS, APPROXIMATELY PARALLEL TO THE MAJOR AXIS APPEAR 0.5", 1.0" AND 3.0" FROM THE INBOARD EDGE THROUGHOUT THE MISSION. A MANUFACTURING SPLICE

17 DEC 1963

~~FRS~~
~~CJS~~
~~SEC~~
~~RES~~
~~ACL~~

(Trace (File))

1

Declassification Review by NGA/DoD

SECRET

25X1

Excluded from automatic
downgrading and
declassification

APPEARS ON FRAME 629 AND IS ASSOCIATED WITH A BAND OF DENDRITIC STATIC DISCHARGES ON FRAME 629. THERE IS A HEAT SPLICE AND ASSOCIATED STATIC DISCHARGES ON FRAME 1776.

D. BOTH SIDES: MINOR PROCESSING STREAKS ARE IN EVIDENCE THROUGHOUT THE MISSION. PINHOLES AND SMALL EMULSION BLISTERS ARE FEW AND INTERMITTENT. THERE ARE 2684 TITLED FRAMES ON EACH SIDE.

E. THERE IS NO MAJOR PROCESSING ANOMALIES.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 15 PER CENT OF THIS MISSION.

S E C R E T

-END OF MESSAGE-

1